A system example according to a measurement purpose < The accessories which are necessary for a measurement purpose are prepared</pre>

1 point of contact pressure measureme	ent	D2	5 point of contact pressure measurement	and Logger	J-5p	Body pressure, bloodstream, a measuring system	
①Main Unit (1ch)	A0101-SET		①Main Unit (Handy type 1ch)	AMI3037-2		①Main Unit (1ch)	A0101-SET
③Air Cylinder AMI3037-CY/⑥Calibration set A	AMI3037-CS		②Extension Unit (2ch) × 2	AMI3037-2B		③Air Cylinder AMI3037-CY/⑥Calibration set AMI3037-CS	
④Air pack sensor 2ea∕pkg	AMI3037-P2		③Air Cylinder	AMI3037-CY		①Laser Blood Flowmeter(flow·mass·vel. For each 1 point)	ALF21R
			④Air pack sensor 5ea/pkg	AMI3037-P5 × 2		48-2 Skin pressure/Blood current Measuring Chamber	A0203
1 point of contact pressure measureme	ent(Handy type)		⑤AC adapter	AMI3037-2AC		48-1Contact surface pressure,Blood flow sensor	A0010T
①Main Unit (Handy type)	AMI3037-2		GCalibration set	AMI3037-CS		⑨Double-sided tape φ15	300 pieces
③Air Cylinder	AMI3037-CY		®Compact Logger(6ch)	AM8051-SET		Continuation angle gauge	DAS-20-SET
④Air pack sensor 2ea/pkg	AMI3037-P2		Carrying case	AMI3037-CA		®10 points measurement Logger and PC	AMI3179S-1
⑤AC adapter	AMI3037-2AC						
Calibration set	AMI3037-CS	E2	5 point of contact pressure measurement	and Logger	L-5p	Body pressure, bloodstream, a measuring system (2c	h)
* need a voltmeter			①Main Unit (5ch)	AMI3037S-5S		①Main Unit (1ch)	A0101-SET
	-		③Air Cylinder	AMI3037-CY		③Air Cylinder AMI3037-CY/⑥Calibration set AMI3037-CS	
1 point of contact pressure measureme	ent and Logger		④Air pack sensor 5ea/pkg	AMI3037-P5 × 2	1	①Main Unit (1ch)	A0101
①Main Unit (1ch)			GCalibration set	AMI3037-CS		①Laser Blood Flowmeter(flow·mass·vel. For each 2 point)	ALF21RD
③Air Cylinder AMI3037-CY/⑥Calibration set AMI3037-	-cs		®Compact Logger(6ch)	AM8051-SET		48-2Skin pressure/Blood current Measuring Chamber	A0203
④Air pack sensor 2ea/pkg	AMI3037-P2				•	48-1Contact surface pressure,Blood flow sensor	A0010T
(BCompact Logger(6ch)	AM8051-SET	F2p	10 point of contact pressure measurement	t and Logger	Ī	⑨Double−sided tape φ15	300 pieces
			①Main Unit (10ch)	AMI3037-10		②Continuation angle gauge	DAS-20-SE
1 point of contact pressure measurement and Logger			③Air Cylinder	AMI3037-CY		®10 points measurement Logger and PC	AMI3179S-1
①Main Unit (Handy type 1ch)	AMI3037-2		④Air pack sensor 5ea/pkg	AMI3037-P5 × 3			
③Air Cylinder	AMI3037-CY		GCalibration set	AMI3037-CS	Q-1p	Body pressure, bloodstream, a measuring system (2ch	+Pressure 8c
④Air pack sensor 2ea/pkg	AMI3037-P2		®10 points measurement Logger and PC	AMI-3179S-10		①Main Unit (10ch)	AMI3037-10
⑤AC adapter	AMI3037-2AC		•			③Air Cylinder	AMI3037-CY
6Calibration set	AMI3037-CS	Gp	20 point of contact pressure measurement	t and Logger		④Air pack sensor 5ea/pkg	AMI3037-P5 >
®Compact Logger(6ch)	AM8051-SET		①Main Unit (20ch)	AMI3037-20		©Calibration set	AMI3037-CS
Carrying case	AMI3037-CA		③Air Cylinder	AMI3037-CY		①Laser Blood Flowmeter(flow·mass·vel. For each 2 point)	ALF21RD
			Air pack sensor 5ea/pkg	AMI3037-P5 × 5		48-2Skin pressure/Blood current Measuring Chamber	A0203
3 point of contact pressure measurement and Logger			©Calibration set	AMI3037-CS		48-1Contact surface pressure,Blood flow sensor	A0010T
①Main Unit (Handy type 1ch)	AMI3037-2		®20 points measurement Logger and PC	AMI3179S-20		⑨Double−sided tape φ15	300 pieces
②Extension Unit (2ch)	AMI3037-2B				_	②Continuation angle gauge	DAS-20-SE
③Air Cylinder	AMI3037-CY					®20 points measurement Logger and PC	AMI3179S-2
h							-

AMI3037-P2

AMI3037-2AC

AMI3037-CS

④Air pack sensor 5ea∕pkg ⑤AC adapter

2007/4

